

## Ghaggar Flood 2010 as viewed on July 19, 20 and 21, 2010



Breach on Sulej-Yamuna Link Canal near Bada Kammi Village in Patiala District of Punjab.

Breach occurred on July 8, 2010

Breach was plugged temporarily.

Water of Pachhisdhara, a tributary of River Ghaggar, entered into Sulej-Yamuna Link Canal through the breach.

SYL canal viewed in the right hand side.

Photograph taken on July 19,2010



SYL Canal near breach site at Jyotisar, Kurukshetra.

Note level of water (the canal is not suppose to carry any water) and its poor maintenance.

Photographed on July 20, 2010



Crop loss due to breach of Sulej-Yamuna Link Canal near Jyotisar, Kurukshetra, Hariyana on July 6, 2010.

Photograph taken on July 20, 2010



Breach on Hansi Butana Canal near Tatiana village, Kaithal District of Haryana on the midnight of July 7, 2010. Ghaggar water breached the Left bank of the canal and then breached the opposite bank also.  
Note the complete breakdown of the canal structure. River water enters from the left hand side and passes through right hand side.  
Photographed on July 21, 2010



Right bank of Hansi Butana Canal and flooded plain



Supervision of repairing work near Tatiana village of Kaithal District in Haryana.



Breach on the right bank of the Hansi Butana Canal near Keorak village in Kaithal District of Haryana. Breach occurred on July 9, 2010. Temporary plugging is noticed. Photograph taken on July 20, 2010



Another breach near Keorak on Hansi Butana Canal. Photograph taken on July 20, 2010.



"After the flood"  
Repetition of transplantation for the second time in monsoon 2010.